



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

VI

OKD 007208747

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME D and K Plating		B. STREET (or other identifier) 4600 N.W. 7th; .8mi north of Reno on Meridian	
C. CITY Oklahoma City	D. STATE OK	E. ZIP CODE 73106	F. COUNTY NAME Oklahoma 109

G. OWNER/OPERATOR (if known) 1. NAME Donald Lehman (operates plating business)		2. TELEPHONE NUMBER (405) 942-3000
--	--	---------------------------------------

H. TYPE OF OWNERSHIP (if known)					
<input type="checkbox"/> 1. FEDERAL	<input type="checkbox"/> 2. STATE	<input type="checkbox"/> 3. COUNTY	<input type="checkbox"/> 4. MUNICIPAL	<input checked="" type="checkbox"/> 5. PRIVATE	<input type="checkbox"/> 6. UNKNOWN

I. SITE DESCRIPTION This is an old <u>plating</u> business consisting of one building with lots of outside storage.
--

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) James Milner R.P.S. Oklahoma City County Health Department	K. DATE IDENTIFIED (mo., day, & yr.) Feb. 1988
--	---

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM On the east side of the building there are numerous rusty, bulging, or turned over drums contents unknown. There is a large rusty storage tank which is rusty. On the westside of the building there is an apparent "dead zone" this could possibly be an area where a spill has occurred.
--

M. PREPARER INFORMATION 1. NAME Robert T. Tassery	2. TELEPHONE NUMBER (405) 271-7099	3. DATE (mo., day, & yr.) March 8, 1988
---	---------------------------------------	--

EPA Form 2070-8 (5-80)

SUPERFUND FILE

90067264

AUG 20 1992



REORGANIZED

10.01
0874700002Reviewed by GH-ES
Date 12/17/88